Sanitized Copy Approved for Release 2009/12/23 : CIA-RDP81T00618R000100730001-8

(16)
------

226

ROUTING									
то	: NAME A	ND ADDRESS		DATE	INITIALS				
1									
2									
3									
4									
	ACTION	DIRECT REPLY		PREPA	RE REPLY				
	APPROVAL	DISPATCH			MENDATION				
	COMMENT	FILE	RETURI		N				
	CONCURRENCE	INFORMATION	1	SIGNAT	TURE				
REMARKS:									
FROM: NAME, ADDRESS, AND PHONE NO.									

SECRET								
	(Seci	ıritv	Class	sificatio	nn)			

25**X**1

CONTROL NO. <u>Z-303537/81</u>

NPIC/PEG (06/81)


Warning Notice
Intelligence Sources and Methods Involved

NATIONAL SECURITY INFORMATION
Unauthorized Disclosure Subject to Criminal Sanctions

\_\_\_\_\_

SECRET

(Security Classification)



Sanitized Copy Approved for Release 2009/12/23: CIA-RDP81T00618R000100730001-8 SECRET 25X1 (c) NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER Attachment to Z-303537/81 Page \_ 1 of \_ 1 NPIC/PEG (6/81) Copy\_\_\_\_ BOMB DAMAGE ASSESSMENT BAGHDAD NUCLEAR RESEARCH CENTER, IRAQ 25X1 1. (S/D) SIGNIFICANCE: ASSESSMENT OF BOMB DAMAGE TO THE FRENCH REACTOR AREA AT BAGHDAD NUCLEAR RESEARCH CENTER. 2. (S/D) REMARKS: DAMAGE IS OBSERVED AT BAGHDAD NUCLEAR RESEARCH THAT THE STRUCTURAL DAMAGE TO CENTER. 25X1 THE ISIS REACTOR BUILDING IS LESS SEVERE THAN PREVIOUSLY REPORTED. THE NORTHEAST SECTION OF THE ROOF OF THE ISIS REACTOR HAS SUSTAINED MINOR DAMAGE. PIECES FROM THE ROOF OF THE OSIRAK REACTOR BUILDING ARE LAYING ON TOP OF THE ISIS REACTOR BUILDING. DAMAGE TO THE INTERIOR OF THE ISIS REACTOR BUILDING CANNOT BE DETERMINED. THE OSIRAK REACTOR BUILDING DOES NOT APPEAR TO HAVE SUFFERED A DIRECT BOMB HIT. THE WALLS ARE WARPED OUT OF ROUND AND PART OF THE ROOF HAS FALLEN THIS DAMAGE IS PROBABLY DUE TO AT LEAST FIVE BOMBS WHICH FELL TO THE EAST OF THE OSIRAK REACTOR BUILDING AND WITHIN THE METAL SCREEN. SOME OF THE INTERIOR COMPONENTS OF THE BUILDING ARE VISIBLE. (S/D) CLEANUP WORK IS NOT OBSERVED AT ANY OF THE DAMAGED BUILDINGS; HOWEVER, PEOPLE ARE AT A GARAGE (NOT ON GRAPHIC) IN THE CENTRAL SECTION OF THE INSTALLATION. THIS GARAGE IS IMMEDIATELY WEST OF THE DESTROYED AND DAMAGED SUPPORT BUILDINGS. (S/D) IN ADDITION TO THE FIVE BOMB CRATERS AT THE OSIRAK REACTOR BUILDING, AN UNDETERMINED NUMBER OF CRATERS ARE IN THE AREA OF THE DESTROYED AND DAMAGED SUPPORT BUILDINGS. ALSO, ONE CRATER IS ON THE WEST SIDE OF LABORATORY TWO AND ONE CRATER IS ON THE WEST SIDE OF LABORATORY ONE (NOT ON GRAPHIC). 25X1 COORDINATES 33-12-26N 044-31-08E COMMENTS AND QUERIES REGARDING THIS BRIEFING BOARD MAY BE DIRECTED TO THE NPIC/PEG OPERATIONS OFFICER. 25X1 These notes have been prepared for briefing purposes only and should not be used for detailed analytical work. Their use should be restricted to the particular briefing board(s) they were prepared for and must be considered valid only for the reporting period as indicated by the date of issue.

WARNING NOTICE Intelligence Sources and Methods Involved

**SECRET** 

25X1